

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

Combination	TFCI	NUMBER OF TrBKS		
		TrCH0	TrCH1	TrCH2
0	0	0	0	0
1	1	1	0	0
2	2	2	0	0
3	3	0	1	0
4	4	1	1	0
5	5	2	1	0
6	6	0	2	0
7	7	1	2	0
8	8	0	0	1
9	9	1	0	1
10	10	2	0	1
11	11	0	1	1
12	12	1	1	1
13	13	0	2	1

FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

Combination	TFCI	NUMBER OF TrBKS			TOTAL NUMBER OF TrBKS
		TrCHO	TrCH1	TrCH2	
0	0	0	0	0	0
1	1	1	0	0	1
2	2	2	0	0	2
3	3	0	1	0	1
4	4	1	1	0	2
5	5	2	1	0	3
6	6	0	2	0	2
7	7	1	2	0	3
8	8	0	0	1	1
9	9	1	0	1	2
10	10	2	0	1	3
11	11	0	1	1	2
12	12	1	1	1	3
13	13	0	2	1	3

FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

BY _____
 PURSUANT TO 37 C.F.R. 1.110
 ON _____
 REC. NO. _____
 FILED BY EXPRESS MAIL
 SHEETS OF DRAWINGS, FIGS. _____
 APPLICANT: _____
 DOCKET NO. _____
 KATTEN MUCHIN SAYS ROSENMAN SLS-840-8000